
HARVE DE GRACE COLORED SCHOOL MUSEUM & CULTURAL CENTER

555 ALLIANCE STREET HAVRE DE GRACE, MARYLAND 21078



3700 Koppers Street, Suite 300 Baltimore, Maryland 21227-1044 Telephone Number: 410-234-8444

PROFESSIONAL CERTIFICATION: RCHITECT UNDER THE LAWS OF THE STATE OF MARYLAND, LICENSE NUMBER 21386, EXPIRATION DA

ALL REPRODUCTION IS PROHIBITED

MUSEUM & CULTURAL CENTER 555 ALLIANCE STREET HAVRE DE GRACE, MD 21078

PROJ. NO:

COVER SHEET

SHEET NO. 1 OF 5

U-

BASE BID

ASBESTOS CONTAINING MATERIALS (ACM) HAVE BEEN IDENTIFIED IN THE BUILT UP ROOFING MATERIALS AND BLACK TAR ASSOCIATED WITH THE FLAT ROOF, PARAPET WALLS, AND CHIMNEYS OF THE 1936 BRICK BUILDING STRUCTURE. AND VALLEY TRANSITION MATERIALS ARE LOCATED UNDER NON-ASBESTOS TPO ROOF COVERING.

CONTRACTOR IS RESPONSIBLE FOR THE COMPLETE REMOVAL, HANDLING, PACKAGING AND DISPOSAL OF IDENTIFIED ACM ROOFING AND TAR MATERIALS FROM THE 1936 BRICK BUILDING STRUCTURE AND VALLEY TRANSITION USING EPA ACCREDITED, MARYLAND LICENSED ASBESTOS ABATEMENT CONTRACTOR/PERSONNEL. ANY ROOF DECKING THAT IS REQUIRED TO BE REPLACED, DUE TO DAMAGE AND SHOWS ASBESTOS CONTAMINATION, MUST BE DISPOSED OF AS SUCH.

CONTRACTOR IS RESPONSIBLE FOR KEEPING ALL INTERIOR AREAS AND EXTERIOR PUBLIC SPACES FREE OF DEBRIS DURING ENTIRE ROOF REMOVAL PROCESS. CARE MUST BE TAKEN IN AREAS WITHIN BUILDING WHERE EXISTING ROOF DAMAGE IS PRESENT.

ALL WORK MUST BE CONDUCTED IN COMPLIANCE WITH EPA 40 CFR PART 61, SUBPART M (NESHAP), OSHA 29 CFR 1926.1101-ASBESTOS IN CONSTRUCTION, COMAR 26.11.21-CONTROL OF ASBESTOS AND SECTION 02 10 00-REMOVAL OF ASEBSTOS CONTAINING ROOFING.

ADDITIONAL ASBESTOS MATERIALS ARE LOCATED WITHIN THE STRUCTURE, WHICH WILL BE ADDRESSED DURING LATER PHASES. REFER TO AMA HAZMAT INSPECTION REPORT(#24185-3/25/2024) FOR ADDITIONAL INFORMATION.

LEAD BASED PAINT (LBP) WAS IDENTIFIED ON METALVENTS LOCATED ON THE ROOF AREA OF1936 BRICK BUILDING STRUCTURE. THESE VENTS WILL BE REPLACED DURING LATER PHASES. IF IMPACTED DURING WORK, CONTRACTOR MUST ADHERE TO OSHA 29 CFR 1926.62-LEAD IN CONSTRUCTION AND EPA 40 CFR 260-268, WASTE CHARACTERIZATION AND DISPOSAL.

ALTERNATE #1

IT IS ASSUMED THAT ASBESTOS ROOFING IS PRESENT UNDER EXISTING SLATE ROOFING OF THE 1912 ORIGINAL WOOD STRUCTURE. CONTRACTOR IS RESPONSIBLE FOR PROVIDING UNIT RATE COST FOR THE REMOVAL AND DISPOSAL OF ASSUMED ASBESTOS ROOFING ASSOCIATED WITH THE 1912 ORIGINAL WOOD STRUCTURE ROOF.

PRIOR TO DISTURBANCE TO THE 1912 ORIGNAL STURCTURE SLATE ROOF, CONTRACTOR SHALL INCLUDE IN THEIR COST FOR AN INDEPENDENT THIRD-PARTY, MARYLAND ACCREDITED AHERA ASBESTOS INSPECTOR TO CONDUCT TESTING OF THE ROOFING MATERIALS ASSOCIATED WITH THE 1912 ORIGINAL STRUCTURE SLATE ROOFING MATERIALS. THE INSPECTOR MUST COLLECT SAMPLES OF ALL SUSPECT ASBESTOS CONTAINING MATERIALS (ACM) TO BE DISTRURBED DURING ALTERNATE 1 WORK: 1912 ORIGNAL STURCTURE SLATE ROOF.

INSPECTOR MUST COLLECT A MINIMUM OF 3 SAMPLES PER SUSPECT MATERIAL ENCOUNTED ON THE ROOF. ALL SAMPLES MUST BE ANALYZED FOLLOWING EPA METHOD 600/R-93/116, BY A NVLAP ACCREDITED LABORATORY. A WRITTEN REPORT SIGNED BY THE MARYLAND ACCREDITED ASBESTOS INSPECTOR WILL BE PROVIDED WITHIN 7 DAYS OF SAMPLE COLLECTION, WITH A DETERMINATION OF ASBESTOS PRESENCE IN THE ROOFING MATERIALS. IF ROOFING IS FOUND TO CONTAIN ASBESTOS, CONTRACTOR MUST REMOVE AND DISPOSE OF AS INDICATED IN BASE BID. IF ROOFING MATERIALS DO NOT CONTAIN ASBESTOS, THE REQUIREMENTS FOR ASBESTOS REMOVAL WILL NOT BE REQUIRED. GENERAL ROOF DEMOLITION AND SAFETY REQUIREMENTS MUST STILL BE ADHERED TO.

LEAD BASED PAINT (LBP) WAS IDENTIFIED ON WOOD SOFFIT AND FASCIA LOCATED ON THE ROOF AREA OF THE 1912 ORIGINAL WOOD STRUCTURE EXTERIOR. THESE SURFACES WILL BE ADDRESSED DURING LATER PHASES. IF IMPACTED DURING WORK, CONTRACTOR MUST ADHERE TO OSHA 29 CFR 1926.62 - LEAD IN CONSTRUCTION AND EPA 40 CFR 260-268, WASTE CHARACTERIZATION AND DISPOSAL.

AEROSOL MONITORING
& ANALYSIS, INC.

1331 ASHTON ROAD, P.O. BOX 646
HANOVER, MARYLAND 21076
WEBSITE: WWW.AMACONSULTING.COM
PHONE: 410-684-3327

ALL REPRODUCTION IS PROHIBITED

CONSULTANTS:

PROJEC

HAVRE DE GRACE COLORED SCHOOL MUSEUM & CULTURAL CENTER 555 ALLIANCE STREET HAVRE DE GRACE, MD 21078

PROJ. NO:	20671
DATE:	4/24/24 BID SET
SCALE:	AS NOTED
REVISION:	

REFERENCE

NORTH

HAZMAT ROOF PLAN

SHEET NO. 2 OF 5


H-1

1936 BRICK STRUCTURE/VALLEY TRANSITION

A) ACM - BUILT-UP ROOFING MATERIALS BENEATH EXISTING TPO MEMBRANE (4,400 SF)
B) ACM - BLACK TAR ON BRICK PARAPET WALLS, ROOF, AND CHIMNEYS (800 SF)
C) LBP - METAL ROOF VENTS (5 VENTS)


1912 ORIGINAL WOOD STRUCTURE


D. SUSPECT ASBESTOS ROOFING AND TAR MATERIALS LOCATED UNDER SLATE SHINGLES AND UNDER TPO MEMBRANE AT ROOF VALLEY (2,400 SF) E. LBP - EXTERIOR WOOD SOFFIT AND FASCIA BOARDS (~300 SF).




ROOF PLAN

SCALE: 1/8"=1'-0"







ALTERNATE #1:

REMOVE EXISTING SLATE ROOFING AND

WOOD DECK FROM DAMAGE.

CONTRACTOR SHALL HAVE

ANALYSIS, INC. IS:

PHONE: 410-684-3327

GARY URBAN

DOCUMENTS.

UNDERLAYMENT IN THEIR ENTIRETY DOWN TO THE

EXISTING WOOD ROOF DECK. PROTECT EXISTING

THE EXISTING UNDERLAYMENT BENEATH THE EXISTING SLATE SHINGLES IS ASSUMED TO BE

THE UNDERLAYMENT SAMPLED AND TESTED BY AEROSOL MONITORING & ANALYSIS, INC.

TO THE REMOVAL OF THE EXISTING SLATE ROOFING.

THE POINT OF CONTACT AT AEROSOL MONITORING &

ASBESTOS CONTAINING MATERIAL. THE

AT THE CONTRACTOR'S EXPENSE, PRIOR

EMAIL: GARYU@AMACONSULTING.COM

REMOVE THE UNDERLAYMENT IN STRICT

COMPLIANCE WITH THE PROCEDURES AND

IF THE SAMPLE TESTS POSITIVE AS AN ABESTOS

CONTAINING MATERIAL, THE CONTRACTOR SHALL

REGULATIONS STIPULATED IN THE CONTRACTOR

SCALE: 1/8"=1'-0"



3700 Koppers Street, Suite 300 Baltimore, Maryland 21227-1044 Telephone Number: 410-234-8444

"PROFESSIONAL CERTIFICATION:
I CERTIFY THAT THESE DOCUMENTS WERE PREPARED OF
APPROVED BY ME, AND THAT I AM A DULY LICENSED
ARCHITECT UNDER THE LAWS OF THE STATE OF
MARYLAND, LICENSE NUMBER 21386, EXPIRATION DATE
01/11/2025 "

ALL REPRODUCTION IS PROHIBITED

CONSULTANTS:

PRO IFCT

HAVRE DE GRACE COLORED SCHOC MUSEUM & CULTURAL CENTER 555 ALLIANCE STREET HAVRE DE GRACE, MD 21078

PROJ. NO:	20671
DATE:	4/24/24 BID SET
SCALE:	AS NOTED
REVISION:	

GENERAL NOTES, BUILDING DATA, & DEMOLITION ROOF PLAN

SHEET NO. 3 OF 5

A-1

EDISTING
CHANNEY

19 RD

19 RD

19 RD

19 RW

2 A

11 AW

DEMOLITION ROOF PLAN

SCALE: 1/8"=1'-0"

BUILDING DATA

INTERNATIONAL MECHANICAL CODE 2018

INTERNATIONAL RESIDENTIAL CODE 2018

INTERNATIONAL ENERGY CONSERVATION CODE 2018

WORK AREA CLASSIFICATION: "ALTERATIONS LEVEL 1"

WORK AREA CLASSIFICATION: "RENOVATIONS"

INTERNATIONAL PLUMBING CODE 2018

INTERNATIONAL FUEL GAS CODE 2018

NFPA 1 FIRE PROTECTION CODE 2018

NATIONAL ELECTRIC CODE 2020

NFPA 101 LIFE SAFETY CODE 2018

COMAR .09.12.5

COMAR 09.12.58

CLASSIFICATION OF WORK


USE GROUP: A-3 MUSEUM


CONSTRUCTION TYPE II-B PER IBC 2018

INTERNATIONAL BUILDING CODE 2018 (SECTIONS AS SPECIFICALLY REFERENCED IN THE IEBC 2018)

INTERNATIONAL EXISTING BUILDING CODE 2018; COMPLIANCE METHOD "WORK AREA COMPLIANCE"

NFPA 101 LIFE SAFETY CODE; CHAPTER 43-EXISTING BUILDING CLASSIFICATION OF THE WORK:







3700 Koppers Street, Suite 300 Baltimore, Maryland 21227-1044 Telephone Number: 410-234-8444

"PROFESSIONAL CERTIFICATION:
I CERTIFY THAT THESE DOCUMENTS WERE PREPARED OR
APPROVED BY ME, AND THAT I AM A DULY LICENSED
ARCHITECT UNDER THE LAWS OF THE STATE OF
MARYLAND, LICENSE NUMBER 21386, EXPIRATION DATE
01/14/2025 "

ALL REPRODUCTION IS PROHIBITED

CONSULTANTS:

PROJECT:

HAVRE DE GRACE COLORED SCHOOL MUSEUM & CULTURAL CENTER 555 ALLIANCE STREET HAVRE DE GRACE, MD 21078

PROJ. NO:	20671
DATE:	4/24/24 BID SET
SCALE:	AS NOTED
REVISION:	

ROOF PLAN

SHEET NO. 4 OF 5

A-2

